

Link do produktu: <https://www.sklep-kia.pl/czujnik-temperatury-wody-carens-ii-iii-iv-ceed-i-ii-iii-cerato-k2500-i-ii-magentis-i-ii-iii-optima-i-ii-picanto-i-ii-p-4066.html>



Czujnik temperatury wody Carens II, III; IV; Ceed I, II, III; Cerato; K2500 I, II; Magentis I, II, III; Optima I, II; Picanto I, II

Cena brutto	55,01 zł
Cena netto	44,72 zł
Stan magazynowy	6 szt
Numer katalogowy	3922038030.OEM*
Producent	INZI Korea

Opis produktu

Czujnik temperatury wody Carens II, III; IV; Ceed I, II, III; Cerato; K2500 I, II; Magentis I, II, III; Optima I, II; Picanto I, II; Pregio II; Rio III, IV; Sorento I, II, III, IV; Soul I, II; Sportage III Korea/Słowacja; Sportage IV, V; Venga; Accent (MC); Atos Prime II; Coupe II, III; Coupe V/Genesis; Elantra I, III, IV; Getz I, II; Grandeur; H-1 Starex/H-200; H-1 Truck; i10 I, II; i20 I, II; i30 I, II; i40; IX20/Getz; IX35 I, II; IX55/Veracruz; Matrix I, II; Santa Fe I, III, IV; Sonata IV, V, VI; Terracan; Trajet; Tucson; Veloster; 39220-38030; 3922039020; 39220-38020;

Carens II - 1.8i;
Carens III - 2.0i (2.0B od 06-2006 do 12-2006);
Carens IV - 1.6GDI, 2.0GDI, CRDI 1.7;
Ceed I, II - 1.4i, 1.6i;
Ceed III - 1.4i, 1.6DGI, CRDI 1.6;
Cerato - 1.6i, CRDI 1.6;
Magentis I - 2.0i;
Magentis II - 2.7i;
Magentis III - CRDI 2.0;
Optima I - 2.0i, 2.0GDI, 2.4i, 2.4GDI, CRDI 1.7;
Optima II - 2.0i, CRDI 1.7;
Picanto I, II - CRDI 1.1;
Rio III - 1.4i, 1.6i, CRDI 1.5;
Rio IV - 1.4i, 1.6i, CRDI 1.1, CRDI 1.4;
Sorento I - 2.4i;
Sorento II - 3.3i;
Sorento III, IV - CRDI 2.0, CRDI 2.2;
Soul I - CRDI 1.6;
Soul II - 1.6MPI, CRDI 1.6;
Sportage III Korea - CRDI 2.0;
Sportage III Słowacja - 2.0i;
Sportage IV - 1.6GDI, CRDI 1.7, CRDI 2.0;
Sportage V - 1.6GDI, 2.0MPI, 2.0GDI, CRDI 1.7, CRDI 2.0;
Venga - 1.4i, 1.6i, CRDI 1.4, CRDI 1.6;
Accent (MC) - 1.4i, 1.6i, CRDI 1.5;
Atos Prime II - 1.1i;
Coupe II - 2.0i, 2.7i;
Coupe III - 2.7i;
Coupe V/Genesis - 2.0i Turbo, 3.8i, 3.8GDI;
Elantra I (XD) - 1.6i, 2.0i, CRDI 2.0;
Elantra III, IV - 1.6i, 1.8i;
Getz I - 1.3i, CRDI 1.5 12V;
Getz II - CRDI 1.5 16V;
Grandeur - 3.3i, 3.8i, CRDI 2.2;

i10 I - 1.2i;
i10 II - 1.0i, 1.2i;
i20 I - CRDI 1.4, CRDI 1.6;
i20 II - 1.2i, 1.4i, CRDI 1.1, CRDI 1.4;
i30 I - CRDI 1.6;
i30 II - 1.4i, 1.6i, 1.6GDI, CRDI 1.4, CRDI 1.6;
i40 - 1.6GDI, 2.0GDI, CRDI 1.7;
IX20/Getz - 1.4i, 1.6i, CRDI 1.4;
IX35 I - 1.6GDI, CRDI 1.7, CRDI 2.0;
IX35 II - 1.6GDI, 2.0GDI, CRDI 1.7, CRDI 2.0;
IX55/Veracruz - 3.8i;
Matrix I - 1.6i, 1.8i, CRDI 1.5 12V i 16V;
Matrix II - 1.6i, 1.8i;
Santa Fe I - 2.4i, CRDI 2.0 (od11-2005);
Santa Fe III, IV - CRDI 2.0, CRDI 2.2;
Sonata IV - 2.0i;
Sonata V - 2.4i, 3.3i, CRDI 2.0;
Sonata VI - CRDI 2.0;
Terracan - 3.5i, 2.5TDI, CRDI 2.9;
Trajet - 2.0i, 2.7i, CRDI 2.0;
Tucson - 2.0i, 2.7i;
Veloster - 1.6GDI;