

Link do produktu: <https://www.sklep-kia.pl/czujnik-temperatury-wody-carens-ii-iii-iv-ceed-i-ii-iii-cerato-k2500-i-ii-magentis-i-ii-iii-optima-i-ii-picanto-i-ii-p-3041.html>



Czujnik temperatury wody Carens II, III; IV; Ceed I, II, III; Cerato; K2500 I, II; Magentis I, II, III; Optima I, II; Picanto I, II

Cena brutto	75,01 zł
Cena netto	60,98 zł
Numer katalogowy	3922038030
Producent	KIA/HYUNDAI

Opis produktu

Czujnik temperatury wody Carens II, III; IV; Ceed I, II, III; Cerato; K2500 I, II; Magentis I, II, III; Optima I, II; Picanto I, II; Pregio II; Rio III, IV; Sorento I, II, III, IV; Soul I, II; Sportage III Korea/Słowacja; Sportage IV, V; Venga; Accent (MC); Atos Prime II; Coupe II, III; Coupe V/Genesis; Elantra I, III, IV; Getz I, II; Grandeur; H-1 Starex/H-200; H-1 Truck; i10 I, II; i20 I, II; i30 I, II; i40; IX20/Getz; IX35 I, II; IX55/Veracruz; Matrix I, II; Santa Fe I, III, IV; Sonata IV, V, VI; Terracan; Trajet; Tucson; Veloster; 39220-38030; 3922039020; 39220-38020;

Carens II - 1.8i;
 Carens III - 2.0i (2.0B od 06-2006 do 12-2006);
 Carens IV - 1.6GDI, 2.0GDI, CRDI 1.7;
 Ceed I, II - 1.4i, 1.6i;
 Ceed III - 1.4i, 1.6DGI, CRDI 1.6;
 Cerato - 1.6i, CRDI 1.6;
 Magentis I - 2.0i;
 Magentis II - 2.7i;
 Magentis III - CRDI 2.0;
 Optima I - 2.0i, 2.0GDI, 2.4i, 2.4GDI, CRDI 1.7;
 Optima II - 2.0i, CRDI 1.7;
 Picanto I, II - CRDI 1.1;
 Rio III - 1.4i, 1.6i, CRDI 1.5;
 Rio IV - 1.4i, 1.6i, CRDI 1.1, CRDI 1.4;
 Sorento I - 2.4i;
 Sorento II - 3.3i;
 Sorento III, IV - CRDI 2.0, CRDI 2.2;
 Soul I - CRDI 1.6;
 Soul II - 1.6MPI, CRDI 1.6;
 Sportage III Korea - CRDI 2.0;
 Sportage III Słowacja - 2.0i;
 Sportage IV - 1.6GDI, CRDI 1.7, CRDI 2.0;
 Sportage V - 1.6GDI, 2.0MPI, 2.0GDI, CRDI 1.7, CRDI 2.0;
 Venga - 1.4i, 1.6i, CRDI 1.4, CRDI 1.6;
 Accent (MC) - 1.4i, 1.6i, CRDI 1.5;
 Atos Prime II - 1.1i;
 Coupe II - 2.0i, 2.7i;
 Coupe III - 2.7i;
 Coupe V/Genesis - 2.0i Turbo, 3.8i, 3.8GDI;
 Elantra I (XD) - 1.6i, 2.0i, CRDI 2.0;
 Elantra III, IV - 1.6i, 1.8i;
 Getz I - 1.3i, CRDI 1.5 12V;
 Getz II - CRDI 1.5 16V;
 Grandeur - 3.3i, 3.8i, CRDI 2.2;
 i10 I - 1.2i;
 i10 II - 1.0i, 1.2i;

i20 I - CRDI 1.4, CRDI 1.6;
i20 II - 1.2i, 1.4i, CRDI 1.1, CRDI 1.4;
i30 I - CRDI 1.6;
i30 II - 1.4i, 1.6i, 1.6GDI, CRDI 1.4, CRDI 1.6;
i40 - 1.6GDI, 2.0GDI, CRDI 1.7;
IX20/Getz - 1.4i, 1.6i, CRDI 1.4;
IX35 I - 1.6GDI, CRDI 1.7, CRDI 2.0;
IX35 II - 1.6GDI, 2.0GDI, CRDI 1.7, CRDI 2.0;
IX55/Veracruz - 3.8i;
Matrix I - 1.6i, 1.8i, CRDI 1.5 12V i 16V;
Matrix II - 1.6i, 1.8i;
Santa Fe I - 2.4i, CRDI 2.0 (od11-2005);
Santa Fe III, IV - CRDI 2.0, CRDI 2.2;
Sonata IV - 2.0i;
Sonata V - 2.4i, 3.3i, CRDI 2.0;
Sonata VI - CRDI 2.0;
Terracan - 3.5i, 2.5TDI, CRDI 2.9;
Trajet - 2.0i, 2.7i, CRDI 2.0;
Tucson - 2.0i, 2.7i;
Veloster - 1.6GDI;