

Link do produktu: <https://www.sklep-kia.pl/lapa-sprzegla-carens-iv-ceed-i-ii-iii-iv-cerato-optima-i-ii-rio-iii-iv-soul-i-ii-sportage-iv-v-venga-p-3693.html>



Łapa sprzęgła Carens IV; Ceed I, II, III, IV; Cerato; Optima I, II; Rio III, IV, V; Soul I, II; Sportage IV, V; Venga

Cena brutto	105,01 zł
Cena netto	85,37 zł
Stan magazynowy	1 szt
Numer katalogowy	4143023200
Producent	KIA/HYUNDAI

Opis produktu

Łapa sprzęgła Carens IV; Ceed I, II, III, IV; Cerato; Optima I, II; Rio III, IV, V; Soul I, II; Sportage IV, V; Venga; Elantra II, III, IV; i20 I, II, III; i30 II, III; i40; IX20/Getz; IX35 I, II; Sonata VII; Tucson II; Veloster; 4143023200; 41430-23200;

Carens IV - 1.6GDI, 2.0GDI, CRDI1.7;
Ceed I, II - 1.4i, 1.6i, 2.0i, CRDI1.6, CRDI2.0;
Ceed III - 1.4i, 1.6GDI, CRDI1.4, CRDI1.6;
Ceed IV - 1.4i, 1.6GDI, 1.0T-GDI; CRDI1.4;
Cerato - 1.6i, CRDI1.6;
Optima I, II - 2.0i;
Rio III - 1.4i, 1.6i od 19-11-2008;
Rio IV, V - 1.4i, CRDI1.1, CRDI1.4;
Soul I - 1.6i, CRDI1.6;
Soul II - 1.6MPI, CRDI1.6;
Sportage IV - 1.6GDI, CRDI1.7;
Sportage V - 1.6GDI, 2.0MPI; 2.0GDI, CRDI1.7;
Venga - 1.4i, 1.6i, CRDI1.4, CRDI1.6;
Elantra II - 1.6i, 2.0i, CRDI1.6;
Elantra III - 1.8i;
Elantra IV - 1.6i, 1.8i;
i20 - 1.4i, 1.6i, CRDI1.4, CRDI1.6;
i20 II, III - 1.4MPI, CRDI1.1, CRDI1.4;
i30 II - 1.4i, 1.6i, 1.6GDI, CRDI1.4, CRDI1.6;
i30 III - 1.4i, 1.6i, 1.6GDI, CRDI1.4;
i40 - CRDI1.7;
IX20/Getz - 1.4i, 1.6i, CRDI1.4;
IX35 I - CRDI1.7;
IX35 II - 1.6GDI, 2.0GDI, CRDI1.7;
Sonata VII - 2.0GDI;
Tucson II - 1.6GDI, 2.0MPI;
Veloster - 1.6GDI;