

Link do produktu: <https://www.sklep-kia.pl/pasek-klinowy-alternatora-carens-iv-ceed-i-ii-iii-optima-i-ii-rio-iii-iv-soul-i-ii-sportage-iv-v-venga-accent-mc-elantra-ii-p-3220.html>



Pasek klinowy alternatora Carens IV;
Ceed I, II, III; Optima I, II; Rio III, IV;
Soul I, II; Sportage IV, V; Venga;
Accent (MC); Elantra II

Cena brutto	40,00 zł
Cena netto	32,52 zł
Stan magazynowy	1 szt
Numer katalogowy	252122A310 (ZF)
Producent	FEBI

Opis produktu

Pasek klinowy alternatora Carens IV; Ceed I, II, III; Optima I, II; Rio III, IV; Soul I, II; Sportage IV, V; Venga; Accent (MC); Elantra II; Getz II; i20 I, II; i30 I, II; i40; IX20/Getz; IX35 I, II;
25212-2A310;
5PK1181;
Carens IV - CRDI 1.7;
Ceed I, II - CRDI1.6 od 02-2008;
Ceed III - CRDI1.4, CRDI1.6;
Optima I, II - CRDI1.7;
Rio III - CRDI1.5 od 07-2009;
Rio IV - CRDI1.4;
Soul I, II - CRDI1.6;
Sportage IV, V - CRDI1.7;
Venga - CRDI1.4, CRDI1.6;
Accent (MC) - CRDI1.5 od 04-2008;
Elantra II - CRDI1.6 od 04-2008 do 02-2009;
Getz II - CRDI1.5 od 04-2008 do 01-2011;
i20 - CRDI1.6, CRDI1.6;
i20 II - CRDI1.1, CRDI1.4;
i30 I - CRDI1.6 od 04-2008;
i40 - CRDI1.7;
IX20/Getz - CRDI1.4;
IX35 I, II - CRDI1.7;